


Erosion-related Considerations

- Community situated where four watercourses meet
- Upstream bedrock cliffs in Mackenzie River
- Thaw-flow slides related to thawing permafrost made worse by riverbank erosion
- Narrow south end of community exposed to riverbank erosion along both sides
- Ice scour and soil weaking after ice jam release may be contributing to erosion



Thaw-flow slide along Mackenzie River (EBA, 2006)




0 1 2 3 Km



Mackenzie River

Main ST

Mackenzie HWY



Overview

Main Map Extent

Mackenzie HWY

0 1 2 3 Km

FORT GOOD HOPE

- Bridges
- Local Streets
- - - Winter Roads
- ▭ Lake
- - - Municipal Boundary



NORTH



July, 2024 Imagery (Vantor, Earthstar Geographics)

0 100 200 300 400 m

