



Erosion-related Considerations

- Kátł'odeeche located alongside meanders of the Hay River delta
- Notable erosion along eastern bank across the river from Terminal C
- Berming and blockage of side channels at Terminal C has likely sent some erosive energy toward reserve lands along the opposite side of the river
- Permafrost not known to be a key contributor to riverbank instability



Location of notable bank erosion (Baird, 2019)



KÁTŁ'ODEECHE

- Highways
- Local Streets
- Trails
- Lake
- Municipal Boundary

NORTH

May, 2024 Imagery (Vantor, Earthstar Geographics)