



Erosion-related Considerations

- Located on a delta of Ndu Tah Deh (Island River) along the southern shore Trout Lake
- Channels tend to change positions every so often within deltas in response to floods and build-up of sediment
- Construction of old airstrip blocked a channel within the delta, which has changed erosion patterns
- The Trout Lake shoreline has not changed much over the past 75 years
- Permafrost not known to be a key contributor to riverbank instability



1950 aerial photo (National Air Photo Library)



SAMBAA K'E

- Resource/Recreation Roads
- Local Streets
- Trails
- - - Winter Roads
- Lake
- - - Municipal Boundary



August, 2021 Imagery (Vantor, Earthstar Geographics)

