



Erosion-related Considerations

- The community sits on a high terrace – the floor of an ancient channel
- Old landslide scar on 40 m-high slope along Mackenzie River
- Uncontrolled surface drainage and erosion of the toe of slope can contribute to instabilities
- Heads of deep gullies are eroding toward airstrip
- Permafrost not known to be a key contributor to riverbank instability



WRIGLEY

— Highways	----- Trails	<p>NORTH</p>
— Bridges	- - - Winter Roads	
Resource/ Recreation Roads	▭ Lake	
— Local Streets	- - - Municipal Boundary	

July, 2024 Imagery (Vantor, Earthstar Geographics)

0 200 400 600 800 1,000 m